

38 516 000 **RAPID SL FOR URINAL**

No exploded view is available for this spare part list.

SPARE PARTS, June 2008 – now

- 1: Holder for outlet elbow (Order-nr. 42236000)
 - 2: Outlet elbow 2" (Order-nr. 42943000)
 - 2.1: Holder for outlet elbow (Order-nr. 42236000)
 - 3: Urinal flush valve for 37 737 (Order-nr. 42758000)
 - 4: Threaded bolt (Order-nr. 43078000)
 - 5: Fixation (Order-nr. 4307500M)
 - 6: Wall brackets (Order-nr. 3855800M)*
- *Special accessories

38 516 000 **RAPID SL FOR URINAL**

No exploded view is available for this spare part list.

SPARE PARTS, June 2003 – June 2008

- 1: Fixing set (Order-nr. 42757000)
 - 2: Holder for outlet elbow (Order-nr. 42236000)
 - 2.1: Hoop (Order-nr. 42949000)
 - 3: Outlet elbow 2" (Order-nr. 42943000)
 - 3.1: Holder for outlet elbow (Order-nr. 42236000)
 - 4: Urinal flush valve for 37 737 (Order-nr. 42758000)
 - 5: Threaded bolt (Order-nr. 43078000)
 - 6: Fixation (Order-nr. 4307500M)
 - 7: Wall brackets (Order-nr. 3855800M)*
- *Special accessories